Authority/Country: FAA/UNITED STATES		AUTHURIZED REI					
		FAA Form 8130-3, AIRWO	5510				
4. Organization Name and Address: AVIATION REPAIR TECHNOLOGIES, LLC. 2305 Texas St, Blytheville, AR 72315 (GKZR792)					5. Work Order/Contract/Invoice Number 32983 / R4122		
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number	:	11. Status/Work:	
1	L/E INTAKE ASS	Y S5411275900001	1	LH3941		REPAIRED	
12. Ren		ATR CMM 71-61-61 REV 19 DATED 01-01-19					
	,						
	_	nnologies, LLC certifies that the work specified in block the product/article is considered ready for release					
13a. Certi	fies the items identified ab	ove were manufactured in conformity to:	14a. X 14 CFR	43.9 Return to Service	e X Ot	her regulation specified in Block 12	
	Approved design dat	Certifies that unless otherwise specified in Block 12, the work identified in Block					
Non-approved design data specified in Block 12.			11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.				
13b. Aut	horized Signature:	13c. Approval/Authorization No.:	14b. Authorize	A / I	14c.	Approval/Certificate No.: GKZR792X	
13d. Nan	ne (Typed or Printed)	13e. Date (dd/mmm/yyyy):	14d. Name:	(Typed or Printed)	14e.	Date (dd/mmm/yyyy):	
			TERRY	Y THRELKELD		14/Jun/2019	
		User/Installer Re					
It is import work in ac	tant to understand that the exicordance with the national reg	stence of this Document alone does not automatically c gulations of an Airworthiness Authority different than the	onstitute authority the Airworthiness A	to install the aircraft/engir uthority of the country sp	ne/propeller/ ecified in bl	article. Where the user/installer performs ock 1, it is essential that	

Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.

the user/installer ensures that his/her Airworthiness Authority accepts aircraft engine(s)/propeller(s)/article(s) from the Airworthiness Authority of the country specified in block 1.

FAA Form 8130-3 (02-14)

1. Approving Civil Aviation

NSN: 0052-00-012-9005

3. Form Tracking Number:

WORK ORDER FORM 104

AVIATION REPAIR TECHNOL(IES, LLC

2305 Texas Street Blytheville, AR 72315 Fax 870-532-6624 870/532-0402

Page No. WORK ORDER:32983-19

Revision#: 06

19/Oct/2012

Location:

Dept#:BU2S

Warranty Code: 00 / 0

Goodthru AD#:

Customer: MA0400 / MASH AEROSPACE,LLC Cust RO#: R4122

Step:PART SHIPPED

Mfg: ATR Outgoing

S5411275900001 / L/E INTAKE A

S/N: LH3941

Incoming P/N: S5411275900001

Incoming S/N: LH3941

Incoming Work Req.: REPAIR

Outgoing Work Req: REPAIR

Manual#: 71-61-61 ATR

RevDate: 01/Jan/2019 Rev#: 19

Reason/Rm:

INSPECT AND CERTIFY

Date Recvd: 21/May/2019

Date Regrd: 04/Jun/2019 Date Estmtd: 11/Jun/2019

PRELIMINARY INSPECTION:

DATE: 22/May/2019

INSPECTOR: TERRY THRELKELD

VERIFY P/N AND S/N

PRE TEST (Yes/No): N

DATE: 22/May/2019

INSPECTOR: TERRY THRELKELD

HIDDEN DAMAGE:

TEARDOWN FINDINGS:

UNIT CLEANED AND INSPECTED AS PER MANUFACTURER'S SPECIFICATIONS.

INSPECTION REVEALED THE FOLLOWING DISCREPANCIES:

- 1. VERIFY P/N AND S/N
- 2. VERIFY UNIT HAS A DATA PLATE INSTALLED.
- 3. INTAKE DE-ICER BOOT REQUIRES A TEST CHECK.
- 4. QTY 12 WASHERS ARE MISSING.
- 5. QTY 1 HOSE FITTING IS CORRODED.
- 6. INTAKE REQUIRES PREP AND PRIMER.
- 7. INTAKE REQUIRES PAINT.

WORK SCOPE RECOMMENDED: REPAIR

*** NOTE ***

THIS IS A REVISED QUOTE.

UNIT IS BEING QUOTED WITH THE FOLLOWING PART(S) BEING PROVIDED

Labor Task Control#

WORK ORDER FORM 10th

AVIATION REPAIR TECHNOL(ES, LLC

2305 Texas Street Blytheville, AR 72315 Fax 870-532-6624 870/532-0402 FAA CRS No:GKZR792X WORK ORDER:32983-19

Revision#: 06

19/Oct/2012

14C 1 131011#1 00

Location:

Dept#:BU2S Locat

Warranty Code: 00 / 0

Goodthru AD#:

Page No.

Customer: MA0400 / MASH AEROSPACE,LLC

Cust RO#: R4122 Mfg: ATR

Step:PART SHIPPED

Outgoing

S5411275900001 / L/E INTAKE A

S/N: LH3941

TEARDOWN FINDINGS:

BY THE CUSTOMER:

- P/N 201-03-194R1-1, HOSE, QTY 1

THIS IS A PRELIMINARY QUOTE - SUBJECT TO FINAL ACCEPTANCE.
THIS QUOTE IS VALID FOR THIRTY (30) DAYS FROM TODAY'S DATE.
IF THIS UNIT IS DECLARED B.E.R., AN EVALUATION FEE WILL BE INVOICED.

UNLESS OTHERWISE DIRECTED TO COMPLY WITH THE OPERATORS SUPPLIED TECHNICAL DATA, OPERATORS MAINTENANCE DOCUMENTS AND TRAINING PROCEDURE OR ANY OTHER SPECIFIC OPERATORS REQUIREMENTS, AVIATION REPAIR TECHNOLOGIES WILL ACCOMPLISH REPAIRS IN ACCORDANCE WITH THE PROCEDURES OUTLINED IN OUR FAA ACCEPTED REPAIR STATION MANUALS.

TECHNICIAN: OLGA BAKER

DATE: 24/May/2019 INSPECTOR: TERRY THRELKELD

FINAL INSPECTION BEFORE ASSEMBLY:

DATE:

INSPECTOR:

CORRECTIVE ACTION:

*

*REPAIRED IAW ATR CMM 71-61-61 REV 19 DATED 01-01-19

TECHNICIAN: O BAKER

DATE: 14/Jun/2019 INSPECTOR: TERRY THRELKELD

MODIFICATION/SERVICE BULLETINS:

Test Data Used:

Test Technician: 1073 O BAKER

Inspector: 1003 T

1003 T THRELKELD

DATE: 14/Jun/2019 DATE: 14/Jun/2019

Final Inspection: 1003 T THRELKELD

DATE: 14/Jun/2019

Technician:

1073 O BAKER

DATE: 14/Jun/2019

Inspector:

1003 T THRELKELD

DATE: 14/Jun/2019

ADDITIONAL COMMENTS:

PARTS DETAIL:

Line# Part Number/Description

W CD RmvCde

Qty Serial Number

1 NAS1169-10

Labor Task Control#

Printed 14/Jun/2019

woostm

08:31:40 ART-023 #

WORK ORDER FORM 100

AVIATION REPAIR TECHNOL(IES, LLC

2305 Texas Street Blytheville, AR 72315 Fax 870-532-6624 870/532-0402

Page No. 3 WORK ORDER:32983-19

Revision#: 06

19/Oct/2012

Dept#:BU2S

Location:

Goodthru AD#:

Warranty Code: 00 / 0

Customer: MA0400 / MASH AEROSPACE,LLC

Cust RO#: R4122

Step:PART SHIPPED

Mfg: ATR Outgoing

S5411275900001 / L/E INTAKE A

S/N: LH3941

-	WASHER	N NE	12.00	
	2 1300L			
1	CONTACT ADHESIVE, 3M	QTS N NE	0.40 OZS	
	3 CONSUMABLE MATERIALS			
	CONSUMABLE MATERIALS	N NE	0.00	
	4 HAZMAT			
	HAZMAT FEE	N NE	0.00	
	5 201-03-194R1-1			
	HOSE	N NE	1.00	
L				1