1. Approving Civil Aviation Authority/Country:	AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: PAZ-61543		
FAA/United States						
4. Organization Name and Address: PAZ AVIATION, INC. 7455 West 2nd. Court Hialeah, Fl. 33014 XPZR185L					5. Work Order/Contract/Invoice Number: Work Order #: 61543 Cust. PO/RO #: 001235	
5. Item: 7. Description:		8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1 STARTER GENERATOR		8260-123	1	299	OVERHAULED	
13a Certifies the items identified N/A Approved design data N/A Non-approved design	tion for safe operation.	14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for				
			return to ser	vice.		
13b.Authorized Signature: N/A	13c. Ap	proval/Authorization No.:	14b. Authorized Signature:		14c. Approval/Certificate No.: XPZR185L	
13d. Name (Typed or Printed): N/A	13e. Dat	te (dd/mmm/yyyy) N/A	14d. Name (Typed or Printed): Ezra Levinstein		14e. Date (dd/mmm/yyyy): 23/Aug/2023	
		User/Ins	staller Responsibiliti	es	l l	
Where the user/installer performs wo	ork in accordance with airworthiness author	ity accepts aircraft article(s) from the a	thiness authority different airworthiness authority of	than the airworthiness auth the country specified in Blo		

PAZ AVIATION, INC.

FAA #: XPZR185L

Work Order #: 61543

Work Order Date: 06/20/2023 Core Return?: Shop #: 2 RO#: 001235 Customer #: 2228 ATA: 24-32-61 MFG: THALES S/N: 299 Desc: STARTER GENERATOR Rev #: 12 Book#: 852 MDL: P/N: 8260-123 **Trouble Reported: NONE** Work Req: OVERHAUL Rec Inspection: DIRTY, PAINT IS WORN & HOUSING SLIGHTLY DENTED. CUSTOMER SUPPLIED COVER & CLA

Special Instructions: REQUIRES LIGHT OH

Preliminary FAA/EASA AD notes inspected - none applicable. Inspection: VERIFIED P/N AND S/N PER DATA PLATE

Hidden NONE APPLICABLE

Damage:

Inspector: A.Y Date: 06/30/2023 Technician: H.P.

Pre Test Passed?: N/A Pre Test?: Yes ☐ No 🗹

Failed Detail: N/A

Teardown UNIT RECEIVED WITH A 5/23 OH TAG. Findings: OPENED AND INSPECTED UNIT.

FOUND UNIT IN FAIR CONDITION NO DISCREPANCIES NOTED.

Workscope Recommended: OVERHAUL

Inspector: A.Y Date: 06/30/2023 Technician: H.P.

Corrective REASSEMBLED AND TESTED.

Action: UNIT PASSED ALL TEST I.A.W. MFR'S SPECIFICATIONS ON C.M.M.

A.T.A. 24-32-61. REV.#12. DATED:10/01/2020 AND IS IN OVERHAUL CONDITION.

AD Notes\SB's: FAA/EASA AD Notes Inspected - None Applicable

Inspector: A.Y Date: 08/23/2023 Technician: H.P.

Final Test: Inspector: A.Y Date: 08/23/2023

Technician: H.P.

Final

Date: 08/23/2023 Inspector: Ezra Levinstein Date: 08/23/2023 Technician: HUGO PERALTA

The appliance\component identified above was serviced in accordance with current regulations of the Federal Aviation Administration, is approved for return to service and is certified as airworthy.

PAZ AVIATION, INC.

FAA #: XPZR185L

Cust# 2228 Cust Name: MASH AEROSPACE, LLC

P/N: 8260-123 Desc: STARTER GENERATOR

MDL:

S/N: 299

Work Order #: 61543

Work Order Date: 06/20/2023

Parts Used: